

# How much sun can a sunshade take?

## Resistance to Fading

Examples of the way in which textiles fade after 160 days exposure to the sun.



Light fastness levels according to DIN EN ISO 105-B02	Resistance to Fading	First noticeable fading after	Discoloration after 160 days of direct sunlight	The GLATZ material classes	The GLATZ product range
Level 1	very poor	5 days			
Level 2	poor	10 days			
Level 3	fair	20 days			
Level 4	fairly good	40 days			
Level 5	good	80 days		2	<i>easy</i> Collection
Level 6	very good	160 days		2	<i>easy</i> Collection
Level 7	excellent	350 days		4 and 5	Individual
Level 8	unbeatable	700 days		5	Individual Professional

- Take note of the light resistance levels when purchasing a sunshade
- Decide in favour of sunshades from 6 to 8
- Protect your sunshade with a cover when not in use